AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 A CH-1844 Villeneuve A +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness inspection certificate - LTF

Inspection certificate number:

PH 304.2020

Impact pad number:

MISC 156.2020

Manufacturer data

Manufacturer name:

Skywalk GmbH & Co. KG

Representative:

Peter Müller

Street: Post code / place: Windeckstrasse 4 83250 Marguarstein

Country:

Germany

Sample data:

Harness

Impact pad

Name: Type:

Core ABS

Impact pad integrated: (1)

Permair B2

Size:

Impact pad type: Weight of Sample [kg]: (1)

Name Impact pad: (1)

Inflatable 0.204

Weight of Sample [kg]: Serial number:

0.546 SPHAWH01-4020-0001

Serial number:(1)

Date of reception:

SACR1C000-VS-0001

Clip-in weight [kg]: Integrated container for 100 n/a

rescue system: Volume container [cm³]:

n/a max n/a min

Date of reception:

18.06.2020

18.06.2020

Test report summary

Structual test

Impact pad test

Result Place Date

POSITIVE Villeneuve 18.06.2020

POSITIVE Villeneuve 18.06.2020

Issue data

Place of declaration:

Villeneuve

Date of issue: Managing Director: 10.09.2020 Andrea Wigger

Signature:

Revision 01: 16.03.2022

This signature approve the validity of the test reports if available; no. 94.21 (test id 02, 03, 13, 09, 04, 14, 07) and no. 94.22 (test id: P, PR) Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

Airworthiness Requirements LTF NfL II 91/09 - EN12491:2015 5.3.2

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.