AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 . CH-1844 Villeneuve . +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness inspection certificate - EN

Inspection certificate number:

PH_276.2019

Impact pad number:

n/a

Impact pad

n/a

n/a

n/a

nla

n/a

n/a

Manufacturer data

Manufacturer name:

Representative: Street:

Post code / place:

Country:

Deimos

Tom Clark 16193 10A, Ave

Surrey, BC Canada, V4A 9R6

Sample	data:	Harness

Name: Type: Size:

Walltee

S-L Weight of Sample [kg]:

Serial number:

Clip-in weight [kg]: Integrated container for rescue system:

Volume container [cm³]:

Test report summary

Date of reception:

120 No

n/a n/a

09.03.2023

Zipline harness

2.42 0202320219

min

max

Impact pad test

Name Impact pad: (1)

Impact pad type:

Serial number: (1)

Date of reception:

Impact pad integrated: (1)

Weight of Sample [kg]: (1)

Result Place Date

POSITIVE Villeneuve 13.03.2023

Structual test

n/a nla

Issue data

Place of declaration:

Date of issue: Managing Director: Villeneuve 23.07.2019

Andrea Wigger

Signature:

Revision 01: 14.03.2023

This revision cancels and replaces the previous one.

This harness is not made for paragliding, climbing or Mountaineering. It has been tested according to the norm EN1651, the purpose of usage is Ziplining.

> This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable) Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards: EN1651:2018+A1:2020(2) and EN12491:2015+A1:2021(2)

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22 The declaration must not be reproduced in part without the written permission of Air Turquoise SA

⁽f) If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

⁽²⁾ These standards are NOT covered by accreditation D-IS-19457-01