# AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 . CH-1844 Villeneuve . +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



# Harness inspection certificate - EN

Inspection certificate number:

PH 444.2024

Impact pad number:

PH 444.2024

#### Manufacturer data

Manufacturer name:

Post code / place:

Gin Gliders Inc.

Representative:

Gin Seok Song

Street:

2318-32, Baegok-daero, Mohyeon-myeon 17036 Cheoin-qu, Yongin-si, Gyeonggi-do

Country:

Rep. of Korea

	100		-		
Car	200	_	~	~+~	
Sar	но	ıe	CI.	ala	Ξ.

#### Harness

# Impact pad

Name: Type: Safari pilot 3

Name Impact pad: (1)
Impact pad integrated: (1)

n/a No

Size:

ABS M

Impact pad type:

Foam 0.44

Weight of Sample [kg]: Serial number: 2.74 SP31311 S Weight of Sample [kg]: (1) Serial number: (1)

SP31311

Clip-in weight [kg]:

120 Yes Date of reception:

13.11.2023

Integrated container for rescue system:

rescue system: Volume container [cm<sup>3</sup>]:

11000 max

6500 min

Date of reception:

13.11.2023

## Test report summary

#### Structual test

### Impact pad test

Result Place Date POSITIVE Villeneuve 15.11.2023

POSITIVE Villeneuve 15.11.2023

#### Issue data

Place of declaration:

Villeneuve

Date of issue: Managing Director: 10.07.2024

Signature:

Alain Zoller

This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020<sup>(2)</sup> and EN12491:2015+A1:2021<sup>(2)</sup>

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22.

The declaration must not be reproduced in part without the written permission of Air Turquoise SA.

<sup>(</sup>f) If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

<sup>(2)</sup> These standards are NOT covered by accreditation D-IS-19457-01