AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 . CH-1844 Villeneuve . +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness inspection certificate - LTF

Inspection certificate number:

PH 272.2019

Impact pad number:

PH 272.2019

Manufacturer data

Manufacturer name:

Sky Paragliders a.s.

Representative:

Michal Sotek

Street: Post code / place: Okruzni 39

Country:

73911 Frydlant n.O. Czech Republic

Sample data:

Harness

Impact pad

Name:

Skylighter 4

Name Impact pad: (1)

n/a

Type:

ABS

Impact pad integrated: (1)

Yes

Size:

L

Impact pad type:

Foam

Weight of Sample [kg]:

3.84

Weight of Sample [kg]: (1)

n/a

Serial number:

2454-13-5834

n/a

Clip-in weight [kg]:

120

Serial number:(1)

Date of reception:

13.03.2019

Integrated container for

Yes

7600 max

3200 min

Date of reception:

rescue system: Volume container [cm3]:

13.03.2019

Test report summary

Impact pad test

Result Place Date

POSITIVE Villeneuve 13.05.2019

Structual test

POSITIVE Villeneuve 13.05.2019

Issue data

Place of declaration:

Villeneuve

Date of issue: Managing Director: 05.03.2020 Alain Zoller

Signature:

This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2) Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:1999, and EN12491:2015 - Airworthiness Requirements LTF NfL II 91/09

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.