para-test.com

Air Turquoise SA Rte du Pré-au-Comte 8 | CH-1844 Villeneuve tel. +41 21 965 65 65 | mobile +41 79 202 52 30 info@para-test.com

Flight test report



					1020
Manufacturer	Escape Gliders	Certification number		PG_0234.2009	
Address	489, route de Grasse 06140 Vence	Date of flight test		03. 04. 2009	
	France				
Representative	None	Place of test		Villeneuve	
Glider model	S'Mile	Classification		В	
		Classification		В	
Trimmer	yes: opened				
	Test pilot	Zoller Alain		Thurnheer Claude	
	Harness	Advance - Bi Pro 2		Sup Air - Evasion M	
	Total weight in flight (kg)	120		210	
1. Inflation/Take-off		Α			
-		Smooth, easy and constant rising	А	Smooth, easy and constant rising	А
Special take off tech	nique required	No	А	No	А
2. Landing		Α			
Special landing techr	nique required	No	А	No	А
3. Speed in straight	flight	В			
Trim speed more that	in 30 km/h	Yes	А	Yes	А
Speed range using the	he controls larger than 10 km/h	Yes	А	Yes	А
Minimum speed		Less than 25 km/h	А	25 km/h to 30 km/h	В
4. Control movement	nt	Α			
Max. weight in flight	up to 80 kg				
Symmetric control pr	essure / travel	not available	0	not available	0
Max. weight in flight	80 kg to 100 kg				
Symmetric control pressure / travel		not available	0	not available	0
Max. weight in flight greater than 100 kg					
Symmetric control pr		Increasing / greater than 65 cm	A	Increasing / greater than 65 cm	A
5. Pitch stability exiting accelerated flight		0			
3		not available	0	not available	0
Collapse occurs		not available	0	not available	0
 Pitch stability op flight 	erating controls during accelerated	0			
Collapse occurs		not available	0	not available	0
7. Roll stability and	damping	Α			
Oscillations		Reducing	А	Reducing	А
8. Stability in gentle	e spirals	Α			
Tendency to return to	o straight flight	Spontaneous exit	А	Spontaneous exit	Α
9. Behaviour in a st	eeply banked turn	В			
Sink rate after two tu	rns	Up to 12 m/s	А	More than 14 m/s	В
10. Symmetric front	t collapse	В			
Entry		Rocking back less than 45°	А	Rocking back less than 45°	Α
Recovery		Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle o	n exit / Change of course	Dive forward 0° to 30° / Keeping course	A	Dive forward 30° to 60° / Keeping course	В
Cascade occurs		No	А	No	А
With accelerator					
Entry		not available	0	not available	0
Recovery		not available	0	not available	0

		•		•
Dive forward angle on exit / Change of course	not available	0	not available	0
Cascade occurs	not available	0	not available	0
11. Exiting deep stall (parachutal stall)	Α			
Deep stall achieved	Yes	Α	Yes	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	А
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
Change of course	Changing course less than 45°	А	Changing course less than 45°	А
Cascade occurs	No	А	No	А
12. High angle of attack recovery	Α			
Recovery	Spontaneous in less than 3 s	A	not available	0
Cascade occurs	No	A	not available	0
13. Recovery from a developed full stall	В			
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 30° to 60°	В
Collapse	No collapse	А	No collapse	А
Cascade occurs (other than collapses)	No	А	No	А
Rocking back	Less than 45°	А	Less than 45°	A
Line tension	Most lines tight	А	Most lines tight	А
14. Asymmetric collapse	В			
With 50% collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	Less than 90° / Dive or roll angle 15° to 45°	A	Less than 90° / Dive or roll angle 15° to 45°	A
Re-inflation behaviour	Spontaneous re-inflation	А	Spontaneous re-inflation	А
Total change of course	Less than 360°	А	Less than 360°	А
Collapse on the opposite side occurs	No	А	No	А
Twist occurs	No	А	No	А
Cascade occurs	No	А	No	А
With 75% collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	90° to 180° / Dive or roll angle 15° to 45°	В	90° to 180° / Dive or roll angle 15° to 45°	В
Re-inflation behaviour	Spontaneous re-inflation	А	Spontaneous re-inflation	А
Total change of course	Less than 360°	А	Less than 360°	А
Collapse on the opposite side occurs	No	А	No	А
Twist occurs	No	А	No	А
Cascade occurs	No	А	No	А
With 50% collapse and accelerator				
, Change of course until re-inflation / Maximum dive forward or roll angle	not available	0	not available	0
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
With 75% collapse and accelerator				
, Change of course until re-inflation / Maximum dive forward or roll angle	not available	0	not available	0
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
15. Directional control with a maintained asymmetric	Α			
collapse				
Able to keep course	Yes	А	Yes	А
180° turn away from the collapsed side possible in 10 s	Yes	А	Yes	А
Amount of control range between turn and stall or spin	More than 50 % of the	А	More than 50 % of the symmetric	А
	symmetric control travel		control travel	
16. Trim speed spin tendency	A		NI-	•
Spin occurs	No	А	No	A

17. Low speed spin tendency	Α			
Spin occurs	No	А	No	А
18. Recovery from a developed spin	Α			
Spin rotation angle after release	Stops spinning in less than 90°	А	Stops spinning in less than 90°	А
Cascade occurs	No	А	No	А
19. B-line stall	Α			
Change of course before release	Changing course less than 45°	А	not available	0
Behaviour before release	Remains stable with straight span	A	not available	0
Recovery	Spontaneous in less than 3 s	А	not available	0
Dive forward angle on exit	Dive forward 0° to 30°	А	not available	0
Cascade occurs	No	А	not available	0
20. Big ears	Α			
Entry procedure	Dedicated controls	А	Dedicated controls	А
Behaviour during big ears	Stable flight	Α	Stable flight	А
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	А
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
21. Big ears in accelerated flight	0			
Entry procedure	not available	0	not available	0
Behaviour during big ears	not available	0	not available	0
Recovery	not available	0	not available	0
Dive forward angle on exit	not available	0	not available	0
Behaviour immediately after releasing the accelerator while maintaining big ears	not available	0	not available	0
22. Behaviour exiting a steep spiral	Α			
Tendency to return to straight flight	Spontaneous exit	Α	Spontaneous exit	Α
Turn angle to recover normal flight	Less than 720°, spontaneous recovery	A	Less than 720°, spontaneous recovery	A
Sink rate when evaluating spiral stability [m/s]	13		24	
23. Alternative means of directional control	Α			
180° turn achievable in 20 s	Yes	А	Yes	А
Stall or spin occurs	No	Α	No	А
24. Any other flight procedure and/or configuration described in the user's manual	0			
Procedure works as described	not available	0	not available	0
Procedure suitable for novice pilots	not available	0	not available	0
Cascade occurs	not available	0	not available	0
25. Comments of test pilot				
Comments			Impossible with B-Line stall	