PG 0764.2013



Ozone Gliders

AIR TURQUOISE SA certified by

Flight test report: EN

Dive forward angle on exit / Change of course

Cascade occurs

With accelerator

Entry

Manufacturer



Manuacturei	Ozone Gilders	Certification number		PG_0704.2013	
Address	2, Queens Drive LA46LN . UK	Date of flight test		17. 10. 2013	
Representative	David Dagault	Place of test		Villeneuve	
Glider model	Mantra M6 MS	Classification		D	
Trimmer		Olassification		D	
minine	no				
	Test pilot	Thurnheer Claude		Zoller Alain	
	Harness	Sup' Air - Altiplume M		Sup'Air - Altiplume M	
	Total weight in flight (kg)	80		95	
1. Inflation/Take-off		С			
Rising behaviour		Overshoots, shall be slowed down to avoid a front collapse	С	Overshoots, shall be slowed down to avoid a front collapse	С
Special take off techniq	ue required	No	Α	No	Α
2. Landing		A			
Special landing technique	ue required	No	Α	No	Α
3. Speed in straight fli	ght	Α			
Trim speed more than 30 km/h		Yes	Α	Yes	Α
Speed range using the controls larger than 10 km/h		Yes	Α	Yes	Α
Minimum speed		Less than 25 km/h	Α	Less than 25 km/h	Α
4. Control movement		Α			
Max. weight in flight up	to 80 kg				
Symmetric control pressure / travel		Increasing / greater than 55 cm	Α	not available	0
Max. weight in flight 80 kg to 100 kg					
Symmetric control pressure / travel		not available	0	Increasing / greater than 60 cm	Α
Max. weight in flight greater than 100 kg					
Symmetric control press	sure / travel	not available	0	not available	0
5. Pitch stability exitin	g accelerated flight	Α			
Dive forward angle on exit		Dive forward less than 30°	Α	Dive forward less than 30°	Α
Collapse occurs		No	Α	No	Α
6. Pitch stability opera flight	ting controls during accelerated	Α			
Collapse occurs		No	Α	No	Α
7. Roll stability and da	mping	Α			
Oscillations		Reducing	Α	Reducing	Α
8. Stability in gentle sp		Α			
Tendency to return to straight flight		Spontaneous exit	Α	Spontaneous exit	Α
9. Behaviour in a stee		В			
Sink rate after two turns		More than 14 m/s	В	More than 14 m/s	В
10. Symmetric front collapse		D			
Entry		Rocking back less than 45°	A	Rocking back less than 45°	A
Recovery		Recovery through pilot action in less than a further 3 s	D	Recovery through pilot action in less than a further 3 s	D

Dive forward 0° to 30° / Keeping

Rocking back less than 45°

course

No

Certification number

Α

Α

Α

A Dive forward 0° to 30° / Keeping

A Rocking back less than 45°

course

Α

Recovery	Recovery through pilot action in less than a further 3 s	D	Recovery through pilot action in less than a further 3 s	D
Dive forward angle on exit / Change of course	Dive forward 0° to 30° / Keeping course	Α	Dive forward 0° to 30° / Keeping course	Α
Cascade occurs	No	Α	No	Α
11. Exiting deep stall (parachutal stall)	Α			
Deep stall achieved	Yes	Α	Yes	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
Change of course	Changing course less than 45°	Α	Changing course less than 45°	Α
Cascade occurs	No	Α	No	Α
12. High angle of attack recovery	A			
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
Cascade occurs	No	Α	No	Α
13. Recovery from a developed full stall	С			
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
Collapse	No collapse	Α	No collapse	Α
Cascade occurs (other than collapses)	No	Α	No	Α
Rocking back	Greater than 45°	С	Greater than 45°	С
Line tension	Most lines tight	Α	Most lines tight	Α
14. Asymmetric collapse	С		-	
With 50% collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	Less than 90° / Dive or roll angle 15° to 45°	Α	Less than 90° / Dive or roll angle 0° to 15°	Α
Re-inflation behaviour	Spontaneous re-inflation	Α	Inflates in less than 3 s from start of pilot action	С
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No	Α	No	Α
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
With 75% collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	90° to 180° / Dive or roll angle 15° to 45°	В	90° to 180° / Dive or roll angle 15° to 45°	В
Re-inflation behaviour	Spontaneous re-inflation	Α	Spontaneous re-inflation	Α
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No	Α	No	Α
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
With 50% collapse and accelerator				
Change of course until re-inflation / Maximum dive forward or roll angle	Less than 90° / Dive or roll angle 15° to 45°	Α	Less than 90° / Dive or roll angle 0° to 15°	Α
Re-inflation behaviour	Spontaneous re-inflation	Α	Inflates in less than 3 s from start of pilot action	С
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No	Α	No	Α
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
With 75% collapse and accelerator				
Change of course until re-inflation / Maximum dive forward or roll angle	90° to 180° / Dive or roll angle 45° to 60°	С	90° to 180° / Dive or roll angle 45° to 60°	С
Re-inflation behaviour	Spontaneous re-inflation	Α	Spontaneous re-inflation	Α
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No	Α	Yes, no turn reversal	С
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
15. Directional control with a maintained asymmetric collapse	Α			
Able to keep course	Yes	Α	Yes	Α
180° turn away from the collapsed side possible in 10 s	Yes	Α	Yes	Α

Amount of control range between turn and stall or spin	More than 50 % of the symmetric control travel	Α	More than 50 % of the symmetric control travel	Α
16. Trim speed spin tendency	Α			
Spin occurs	No	Α	No	Α
17. Low speed spin tendency	A			
Spin occurs	No	Α	No	Α
18. Recovery from a developed spin	С			
Spin rotation angle after release	Stops spinning in 90° to 180°	С	Stops spinning in less than 90°	Α
Cascade occurs	No	Α	No	Α
19. B-line stall	С			
Change of course before release	Changing course less than 45°	Α	Changing course less than 45°	Α
Behaviour before release	Remains stable with straight span	Α	Remains stable without straight span	С
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in 3 s to 5 s	В
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
Cascade occurs	No	Α	No	Α
20. Big ears	В			
Entry procedure	Dedicated controls	Α	Dedicated controls	Α
Behaviour during big ears	Stable flight	Α	Stable flight	Α
Recovery	Recovery through pilot action in less than a further 3 s	В	Spontaneous in 3 s to 5 s	В
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
21. Big ears in accelerated flight	В			
Entry procedure	Dedicated controls	Α	Dedicated controls	Α
Behaviour during big ears	Stable flight	Α	Stable flight	Α
Recovery	Recovery through pilot action in less than a further 3 s	В	Recovery through pilot action in less than a further 3 s	В
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
Behaviour immediately after releasing the accelerator while maintaining big ears	Stable flight	Α	Stable flight	Α
22. Behaviour exiting a steep spiral	D			
Tendency to return to straight flight	Turn remains constant	D	Turn remains constant	D
Turn angle to recover normal flight	With pilot action	D	With pilot action	D
Sink rate when evaluating spiral stability [m/s]	18		20	
23. Alternative means of directional control	A			
180° turn achievable in 20 s	Yes	Α	Yes	Α
Stall or spin occurs	No	Α	No	Α
24. Any other flight procedure and/or configuration described in the user's manual	0			
Procedure works as described	not available	0	not available	0
Procedure suitable for novice pilots	not available	0	not available	0
Cascade occurs	not available	0	not available	0
25. Comments of test pilot				
Comments	Symmetrischer Frontklapper und einseitiger Klapper wurden beschleunigt mit Faltleinen getestet		Tested with "Folding Lines" for front & asymetric collapses	