AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 . CH-1844 Villeneuve . +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Miscellaneous Impact Pad Report

Inspection certificate number: MISC_185.2021

Manufacturer data:

Supair SAS

Parc Altais / 34, rue Adrastée

Manufacturer name: Representative:

Laurent Chiabaut

Street:

Post code place:

Country:

74650 Chavanod **France**

Not related to specific model

Harness model:

Sample data:

Name impact pad:

Emergency parachute integrated: Impact pad type:

Serial number:

Weight of sample [kg]:

Date of test:

Bump 16STK A2

Yes Foam

Bump 16STK A2 #1

0.486

19.04.2021

Atmosphere AGL:

[C°]	19	
RH [%]	32	
[hPa]	1007	

Summary of Impact pad test (1)

Test id	-	Test configuration (2)	Max Peak of Impact [g] ⁽³⁾	Duration at 38 [g] in [ms] (4)	Duration at 20 [g] in [ms] ⁽⁵⁾	Diff. of test 1 and 2 [%] (6)	Result
Р	V	Test sample attached to dummy in flying position, without emergency parachute	36.22	0.00	17.50	1.49	POSITIVE
PR	٧	Test sample attached to dummy in flying position, Include emergency parachute	37.24	0.00	17.50	2.39	POSITIVE

Issue data

Place of declaration Date of issue: Managing director

Villeneuve 19.05.2021 Alain Zoller

Signature:



This signature approve the validity of the test reports if available. Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

Airworthiness Requirements LTF NfL II 91/09 - European Standard EN1651 :2018

This declaration must not be reproduced in part without the written permission of AIR TURQUOISE SA.

⁽¹⁾ Calculated value in tests reports include the value minus the uncertainty (on safe side) / The uncertainty stated is the expanded uncertainty obtained by multiplying the standard uncertainty by the coverage factor k = 2. The value of the measurand lies within the assigned range of values with a probability of 95%.

⁽²⁾ The dummy is lifted minimum up to 1.65 m, and impact pad is mounted on. Where the impact occurs, measure distance from bottom of impact pad to ground.

⁽³⁾ Maximum peak of impact should be less or equal to 50 [g], (4) If any, the maximum duration in at 38 [g] should be less or equal to 7 [ms], (5) If any, the maximum duration in at 20 [g] should be less or equal to 25 [ms]. (6) The test should be done twice, and the 2nd test the maximum peak should not differe more than 20% from the first test, maximum peak.

AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 * CH-1844 Villeneuve * +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Inspection certificate number:

MISC_185.2021

Name impact pad:

Bump 16STK A2

Test results of Impact pad test

	without emergency parachute		include emergency parachute	
	P1	P2	PR1	PR2
Maximum Peak of impact [g]	35.69	36.22	34.86	37.24
Impact duration at +38 [g] in [ms]	0.00	0.00	0.00	0.00
Impact duration at +20 [g] in [ms]	17.50	17.50	17.50	17.50
Uncertainty k=2[g]	2.05	2.08	2.01	2.14
Difference of test 1 and 2 [%]	100.00	101.49	100.00	106.85

