## AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 🔺 CH-1844 Villeneuve 🔺 +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



## **Harness inspection certificate - EN**

Inspection certificate number: PH 389.2023 Impact pad number: PH 389.2023

Manufacturer data

Manufacturer name: Woody Valley srl Simone Caldana Representative: Via Linz 23 Street: Post code / place: **38121 Trento** 

Country: Italy

Sample data: **Harness** Impact pad

Name Impact pad: (1) **ASROC** n/a Name: Impact pad integrated: (1) ABS No Type: Impact pad type: Foam М Size: Weight of Sample [kg]: (1) 7.00 1.46 Weight of Sample [kg]:

Serial number: (1) 112 0115 001P\_S 112 0115 001P Serial number:

Clip-in weight [kg]: 120

Integrated container for Yes

rescue system:

Volume container [cm<sup>3</sup>]: **5600** max

5200 min

10.02.2023 Date of reception:

**Test report summary** Structual test Impact pad test

**POSITIVE POSITIVE** Result Villeneuve Villeneuve Place 10.02.2023 12.12.2023 Date

Issue data

Place of declaration: Villeneuve 13.02.2023 Date of issue: **Andrea Wigger** 

Managing Director:

Signature:

Revision 01: 24.01.2024

Date of reception:

This revision cancels and replaces the previous one.

10.02.2023

This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020(2) and EN12491:2015+A1:2021(2)

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22 The declaration must not be reproduced in part without the written permission of Air Turquoise SA

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

<sup>(2)</sup> These standards are NOT covered by accreditation D-IS-19457-01