## AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 . CH-1844 Villeneuve . +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



## **Harness inspection certificate - EN**

Inspection certificate number:

PH 468.2025

Impact pad number:

MISC\_299.2025

## Manufacturer data

Manufacturer name:

**ASCENDANT** 

Representative:

**Hugo Laronze** 

Street:

103 Route des Nants

Post code / place:

74540 Saint Felix

Country:

France

Samp	le data:
- cp	

Harness

Impact pad

Name:

ZIAN

Name Impact pad: (1)

Coussin A

Type:

ABS

Impact pad integrated: (1)

No

Size:

Impact pad type:

Inflatable

Weight of Sample [kg]:

1.16

Weight of Sample [kg]: (1)

17.02.2025

Serial number:

**AAZI24K001** 

Serial number: (1)

Date of reception:

KT25017209-0

ISO 94 20h

Clip-in weight [kg]: Integrated container for 100 Yes

Volume container [cm3]:

5000 max

2000 min

Date of reception:

rescue system:

21.11.2024

Test report summary

Structual test

Impact pad test

Result Place Date

**POSITIVE** Villeneuve 07.02.2025

**POSITIVE** Villeneuve 17.02.2025

## Issue data

Place of declaration:

Date of issue:

Villeneuve

21.02.2025

Managing Director:

Andrea Wigger

Signature:

Rev 04 | 04.03.2022

This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020(2) and EN12491:2015+A1:2021(2)

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22 The declaration must not be reproduced in part without the written permission of Air Turquoise SA

Page 1 of 1

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

<sup>(2)</sup> These standards are NOT covered by accreditation D-IS-19457-01