AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 * CH-1844 Villeneuve * +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness inspection certificate - NfL

Inspection certificate number:

PH 445.2024

Impact pad number:

PH 445.2024

Manufacturer data

Manufacturer name:

Gin Gliders Inc.

Representative:

Gin Seok Song

Street:

2318-32, Baegok-daero, Mohyeon-myeon

Post code / place:

17036 Cheoin-gu, Yongin-si, Gyeonggi-do

Country:

Rep. of Korea

Sar	mml		1-4-	
Sai	по	6 0	апа	10

Harness

Impact pad

Name: Type: Safari passenger 3 ABS Name Impact pad: (1)
Impact pad integrated: (1)

Yes Airbag

Size:

M

Impact pad type:

Airbag n/a

Weight of Sample [kg]: Serial number: 2.20 SPA31311 S Weight of Sample [kg]: (1)
Serial number: (1)

SPA31311

Clip-in weight [kg]:

120 No

Date of reception:

13.11.2023

Integrated container for rescue system:

Volume container [cm³]:

n/a max

n/a min

Date of reception:

13.11.2023

Test report summary

Structual test

Impact pad test

Result Place Date

POSITIVE Villeneuve 15.11.2023 POSITIVE Villeneuve 15.11.2023

Issue data

Place of declaration:

Villeneuve

Date of issue:

10.07.2024

Managing Director:

Alain Zoller

Signature:

This signature approve the validity of the test reports 94.21a and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

NfL 2-565-20. EN12491:2015 and EN1651:1999

The certificate of inspection is completed with test reports, if available, number: 94.21a and 94.22

The declaration must not be reproduced in part without the written permission of AIR TURQUOISE SA

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag. (2) If harness has an integrated inner container for emergency parachute, extra deployment tests are done.