AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 🔺 CH-1844 Villeneuve 🔺 +41 (0)2) 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Harness Impact Pad Report

spection certificate number: PH_192.2017

Manufacturer data: Sample data:

Manufacturer name: Gin Gliders Inc. Name impact pad: Yeti convertible 2 Airbag

Representative: Gin Seok Song Impact pad intgrated: No
Street: 2318-32, Baegok-daero, Mohyeon-myeon Impact pad type: Airbag
Post code place: Cheoin-gu, Yongin-si, Gyeonggi-do Weight of sample [kg]: 0.46
Country: 17036, Rep. of Korea Serial number: YCA002

Date of test: 05.07.2022

Harness model: Yeti convertible 2

Atmosphere AGL:

Temp.	[C°]	25
R.H.	[%]	50
Press.	[hPa]	1010

Summary of Impact pad test (1)

	_		Max Peak of Impact	Duration at 38 [g]	Duration at 20	Diff. of test 1	
Test id		Test configuration (2)	[g] ⁽³⁾	in [ms] ⁽⁴⁾	[g] in [ms] ⁽⁵⁾	and 2 [%] ⁽⁶⁾	Result
Р	٧	Test sample attached to dummy in flying position, without emergency	23.49	0.00	14.17	-4.43	POSITIVE
PR	٧	Test sample attached to dummy in flying position, Including emergency	27.79	0.00	15.00	12.50	POSITIVE

Manufacture	Instrument	Type no	S/N	Validity Calibration
Burster/MTS	Accelerometer 100 g	89010-100	1263567	23.01.2024
JDC elec	Geos n°11 Skywatch	Geos n°11	Unit11	18.06.2025

The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20a or 94.20b

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

NfL 2-565-20 and EN1651:2018+A1:2020⁽⁷⁾

⁽¹⁾ Calculated values in tests reports include the value minus the uncertainty (on safe side) / The uncertainty stated is the expanded uncertainty obtained by multiplying the standard uncertainty by the coverage factor k = 2. The value of the measurand lies within the assigned range of values with a probability of 95%

⁽²⁾ The dummy is lifted minimum up to 1.65 m, and impact pad is mounted on. Where the impact occurs, measure distance from bottom of impact pad to ground

⁽³⁾ Maximum peak of impact should be less or equal to 50 [g], (4) If any, the maximum duration in at 38 [g] should be less or equal to 7 [ms], (5) If any, the maximum duration in at 20 [g] should be less or equal to 25 [ms]. (6) The test should be done twice, and the 2nd test the maximum peak should not differe more than 20% from the first test, maximum peak.

 $^{^{(7)}}$ This standard is NOT covered by accreditation D-IS-19457-01

This declaration must not be reproduced in part without the written permission of AIR TURQUOISE SA

AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 🔺 CH-1844 Villeneuve 🔺 +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Inspection certificate number: PH_192.2017 Name impact pad: Yeti convertible 2 Airbag

Test results of Impact pad test

	without emergency parachute		including emergency parachute	
	P1	P2	PR1	PR2
Maximum peak of impact [g]	23.49	22.45	24.70	27.79
Impact duration at +38 [g] in [ms]	0.00	0.00	0.00	0.00
Impact duration at +20 [g] in [ms]	14.17	10.83	15.00	13.33
Uncertainty k=2 [g]	1.35	1.29	1.42	1.60
Diff. between test 1 and 2 [%]	100.00	95.57	100.00	112.50

