



Harness inspection certificate

Inspection certificate number: **PH_286.2019**

Impact pad number: **PH_286.2019**

Manufacturer data

Manufacturer name: **Woody Valley srl**
 Representative: **Simone Caldana**
 Street: **Via Vienna 92**
 Post code / place: **30121 Trento**
 Country: **Italy**

Sample data:

Harness

Impact pad

Name:	Wani Light 2	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	M	Impact pad type:	Airbag
Weight of Sample [kg]:	2.94	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	096 0014 0002	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	17.09.2019
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			
	5000 max		
	n/a min		
Date of reception:	17.09.2019		

Test report summary

Structual test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	17.09.2019	17.09.2019

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **22.11.2019**
 Managing Director: **Randi Eriksen**
 Signature: 

This signature approve the validity of the test reports if available: no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

Airworthiness Requirements LTF NFL II 91/09 chapter 4.2.1, 5, 6.1.5 and 6.1.8

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22