

Harness inspection certificate - EN

Inspection certificate number: PH_338.2021

Impact pad number: n/a

Manufacturer data

Manufacturer name: Dudek Paragliders SJ
 Representative: Wojciech Domanski
 Street: Ul. Centralna 2U
 Post code / place: 86-031 Osielsko
 Country: Poland

Sample data:

Harness

Impact pad

Name:	Powerseat Light	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	n/a
Size:	L	Impact pad type:	n/a
Weight of Sample [kg]:	2.36	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	H-13061	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	n/a
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			
			5800 max
			4600 min
Date of reception:	26.03.2021		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	n/a
Place	Villeneuve	n/a
Date	19.05.2021	n/a

Issue data

Place of declaration: Villeneuve
 Date of issue: 07.07.2021
 Managing Director: Andrea Wigger
 Signature: 

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available, no. 94.21b (test id 01,03,05,06,06,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)
 Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:2018 and EN12491:2015

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22