

Harness inspection certificate - EN

Inspection certificate number: **PH_347.2021**Impact pad number: **n/a**

Manufacturer data

Manufacturer name: **Woody Valley srl**
 Representative: **Simone Caldana**
 Street: **Via Vienna 92**
 Post code / place: **30121 Trento**
 Country: **Italy**

Sample data:

Harness

Impact pad

Name:	Crest	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	M	Impact pad type:	Airbag
Weight of Sample [kg]:	1.48	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	106 0115 0002	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	21.09.2021
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			
			5200 max
			4100 min
Date of reception:	21.09.2021		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	23.09.2021	27.09.2021

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **28.09.2021**
 Managing Director: **Alain Zoller**
 Signature: 

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)

Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1661:2018** and **EN12491:2016**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22