

# Harness inspection certificate - EN

Inspection certificate number: PH\_344.2021

Impact pad number: n/a

## Manufacturer data

Manufacturer name: **Davinci Products Inc.**  
 Representative: **Jihun Lee**  
 Street: **53 sinchon-gil, Okcheon-myeon, Yangpyeong-gun**  
 Post code / place: **Gyeonggi-do 12505**  
 Country: **Republic of Korea**


## Sample data: Harness Impact pad

Name:	<b>Duo</b>	Name Impact pad: <sup>(1)</sup>	<b>n/a</b>
Type:	<b>ABS</b>	Impact pad integrated: <sup>(1)</sup>	<b>Yes</b>
Size:	<b>M</b>	Impact pad type:	<b>Airbag</b>
Weight of Sample [kg]:	<b>2.8</b>	Weight of Sample [kg]: <sup>(1)</sup>	<b>n/a</b>
Serial number:	<b>HDO-TFM-21002</b>	Serial number: <sup>(1)</sup>	<b>n/a</b>
Clip-in weight [kg]:	<b>120</b>	Date of reception:	<b>18.02.2021</b>
Integrated container for rescue system:	<b>Yes</b>		
Volume container [cm <sup>3</sup> ]:			<b>6500 max</b> <b>5500 min</b>
Date of reception:	<b>18.02.2021</b>		

## Test report summary Structural test Impact pad test

Result	<b>POSITIVE</b>	<b>POSITIVE</b>
Place	<b>Villeneuve</b>	<b>Villeneuve</b>
Date	<b>04.03.2021</b>	<b>25.02.2021</b>

## Issue data

Place of declaration: **Villeneuve**  
 Date of issue: **29.09.2021**  
 Managing Director: **Andrea Wigger**  
 Signature: 

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)  
 Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:  
 European Standard **EN1651:2018** and **EN12491:2015**

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22