

Harness inspection certificate - EN

Inspection certificate number: PH_350.2021

Impact pad number: PH_350.2021

Manufacturer data

Manufacturer name: **Sky Country**
 Representative: **Rakov Alexey**
 Street: **Astronomicheskaya street 27-29**
 Post code / place: **61085 Kharkov**
 Country: **Ukraine**

Sample data: Harness Impact pad

Name:	Vector 3	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	L	Impact pad type:	Foam
Weight of Sample [kg]:	3.82	Weight of Sample [kg]: ⁽¹⁾	0.54
Serial number:	1121-001-S	Serial number: ⁽¹⁾	1121-001
Clip-in weight [kg]:	120	Date of reception:	22.11.2021
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			8100 max 3000 min
Date of reception:	22.11.2021		

Test report summary Structural test Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	24.11.2021	26.11.2021

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **20.12.2021**
 Managing Director: **Andrea Wigger**
 Signature:



"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)
 Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:2018 and EN12491:2015

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22