

Harness inspection certificate - EN

Inspection certificate number: **PH_399.2023**Impact pad number: **MISC_243.2023**

Manufacturer data

Manufacturer name: **Nova Vertriebsgesellschaft m.b.H.**
 Representative: **Philipp Medicus**
 Street: **Auweg 14**
 Post code / place: **6124 Terfens**
 Country: **Austria**

Sample data: Harness Impact pad

Name:	ARTUS Light 2023	Name Impact pad: ⁽¹⁾	Alumina
Type:	ABS	Impact pad integrated: ⁽¹⁾	No
Size:	M/L	Impact pad type:	Aluminium
Weight of Sample [kg]:	1.20	Weight of Sample [kg]: ⁽¹⁾	0.23
Serial number:	PX001	Serial number: ⁽¹⁾	ALU010.2
Clip-in weight [kg]:	100		
Integrated container for rescue system:	Yes	Date of reception:	16.08.2021
Volume container [cm ³]:			
			3100 max
			2300 min
Date of reception:	09.11.2020		

Test report summary Structural test Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	09.11.2020	16.08.2021

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **08.03.2023**
 Managing Director: **Andrea Wigger**
 Signature:



This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020⁽²⁾ and EN12491:2015+A1:2021⁽²⁾

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag

⁽²⁾ These standards are NOT covered by accreditation D-IS-19457-01

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22

The declaration must not be reproduced in part without the written permission of Air Turquoise SA