



Harness inspection certificate - EN

Inspection certificate number: PH_357.2022

Impact pad number: **MISC 156.2020**

Manufacturer data

Manufacturer name: Skywalk GmbH & Co. KG
Representative: Mr. Arne Wehrlin
Street: Windeckstrasse 4
Post code / place: 83250 Marquarstein
Country: Germany

Sample data:

Harness

Impact pad

| | |
|---|----------------------|
| Name: | Breeze 2 |
| Type: | ABS |
| Size: | M |
| Weight of Sample [kg]: | 2.24 |
| Serial number: | SHBR2M005 |
| Clip-in weight [kg]: | 120 |
| Integrated container for rescue system: | Yes |
| Volume container [cm ³]: | 5600 max 2000 min |
| Date of reception: | 26.10.2021 |

| | |
|---------------------------------------|-------------------|
| Name Impact pad: ⁽¹⁾ | Permair B2 |
| Impact pad integrated: ⁽¹⁾ | No |
| Impact pad type: | Inflatable |
| Weight of Sample [kg]: ⁽¹⁾ | 0.204 |
| Serial number: ⁽¹⁾ | SACR1COOO-VS-0001 |
| Date of reception: | 18.06.2020 |

Test report summary


Structural test

Impact pad test

| | |
|--------|-------------------|
| Result | POSITIVE |
| Place | Villeneuve |
| Date | 05.03.2024 |

POSITIVE
Villeneuve
18.06.2020

Issue data

Place of declaration: Villeneuve
Date of issue: 09.08.2023
Managing Director: Andrea Wigger
Signature: 

Revision 01: 05.03.2024
This revision cancels and replaces the previous one.

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available: no. 94.21b (test id 01.03.05.06.08.09.10.11.12.14.RRDT.RRST) and no. 94.22 (test id: P.PR)

Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:2018 and EN12491:2015

(1) If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22