



Harness inspection certificate - EN

Inspection certificate number: **PH_328.2021**

Impact pad number:

Manufacturer data

Manufacturer name: **Flugsau GmbH**
 Representative: **Andre Bernhard**
 Street: **Aelplerhaus 3**
 Post code / place: **6388 Grafenort**
 Country: **Switzerland**

Sample data:

Harness

Impact pad

Name:	Gigi	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	n/a
Size:	M	Impact pad type:	n/a
Weight of Sample [kg]:	0.232	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	280121/02	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	n/a
Integrated container for rescue system:	n/a		
Volume container [cm ³]:			n/a max n/a min
Date of reception:	09.02.2021		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	n/a
Place	Villeneuve	n/a
Date	16.02.2021	n/a

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **25.03.2021**
 Managing Director: **Alain Zoller**
 Signature: 

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)

Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651:2018** and **EN12491:2015**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22