

Harness inspection certificate - EN

Inspection certificate number: **PH_403.2023**Impact pad number: **MISC_304.2025**

Manufacturer data

Manufacturer name: **Neo SAS**
 Representative: **Eric Roussel**
 Street: **ZA des Vernays**
 Post code / place: **74210 Doussard**
 Country: **France**

Sample data:

Harness

Impact pad

Name: **SUSPENDER 2.0**
 Type: **ABS**
 Size: **L**
 Weight of Sample [kg]: **4.7**
 Serial number: **K16005**
 Clip-in weight [kg]: **120**
 Integrated container for rescue system: **Yes**
 Volume container [cm³]: **7400** max
2500 min
 Date of reception: **08.12.2022**

Name Impact pad: ⁽¹⁾ **Neo Koroyd 3.1**
 Impact pad integrated: ⁽¹⁾ **No**
 Impact pad type: **Koroyd**
 Weight of Sample [kg]: ⁽¹⁾ **0.42**
 Serial number: ⁽¹⁾ **NK3.1.001**
 Date of reception: **31.01.2025**

Test report summary

Structural test

Impact pad test

RDT / RST

Result:
Remark:

POSITIVE**POSITIVE****POSITIVE**

Place:
Date:


Villeneuve
05.07.2023

Villeneuve
31.01.2025

Villeneuve
05.07.2023

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **23.09.2025**
 Managing Director: **Andrea Wigger**
 Signature:



This signature approve the validity of the test reports 94.21b and 94.22 (only if test reports are applicable)

Air Turquoise SA, has thoroughly tested the sample mentioned above and certifies its conformity with the following standards:

EN1651:2018+A1:2020 and EN12491:2015+A1:2021

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag

The certificate of inspection is completed with test reports, if available, number: 94.21b and 94.22

The declaration must not be reproduced in part without the written permission of Air Turquoise SA