

# Harness inspection certificate - NFL

Inspection certificate number: PH\_421.2023

Impact pad number: MISC\_243.2023

## Manufacturer data

Manufacturer name: **Nova Vertriebsgesellschaft m.b.H.**  
 Representative: **Philipp Medicus**  
 Street: **Auweg 14**  
 Post code / place: **6124 Terfens**  
 Country: **Austria**

## Sample data:

Harness	Impact pad
Name: <b>ARTUS</b>	Name Impact pad: (1) <b>ALUMINA</b>
Type: <b>ABS</b>	Impact pad integrated: (1) <b>No</b>
Size: <b>M</b>	Impact pad type: <b>Aluminium</b>
Weight of Sample [kg]: <b>2.10</b>	Weight of Sample [kg]: (1) <b>0.23</b>
Serial number: <b>AR12001</b>	Serial number:(1) <b>ALU010.2</b>
Clip-in weight [kg]: <b>130</b>	Date of reception: <b>16.08.2021</b>
Integrated container for rescue system: <b>Yes</b>	
Volume container [cm3]:	<b>4300 max</b> <b>2300 min</b>
Date of reception: <b>24.01.2022</b>	

## Test report summary

	Structural test	Impact pad test
Result:	<b>POSITIVE</b>	<b>POSITIVE</b>
Place:	<b>Villeneuve</b>	<b>Villeneuve</b>
Date:	<b>11.05.2023</b>	<b>16.08.2021</b>

## Issue data

Place of declaration: **Villeneuve**  
 Date of issue: **25.10.2023**  
 Managing Director: **Andrea Wigger**  
 Signature:



This signature approves the validity of the test reports if available; no. 94.21 (test id 02, 03, 13, 09, 04, 14, 07) and no. 94.22 (test id: P, PR)  
**Air Turquoise SA**, having thoroughly assessed the sample mentioned above, declares it was found conform with all requirements defined by the following norms:

**NFL 2-565-20, EN12491:2015 and EN1651:1999**

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag. <sup>(2)</sup> If harness has an integrated inner container for emergency parachute, extra deployment tests are done for different type of emergency parachute.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contains the following test and is complet with the test, if available, report: 94.21 and 94.22