

## Harness inspection certificate - EN

Inspection certificate number: PH\_294.2020

Impact pad number: MISC\_225.2022

### Manufacturer data

Manufacturer name: **Ozone Gliders LTD**  
 Representative: **Russell Ogden**  
 Street: **16 Barnes Green**  
 Post code / place: **EH54 8PP Livingston**  
 Country: **Scotland UK**

### Sample data:

#### Harness

#### Impact pad

Name:	<b>Submarine</b>	Name Impact pad: <sup>(1)</sup>	<b>Submarine Protector</b>
Type:	<b>ABS</b>	Impact pad integrated: <sup>(1)</sup>	<b>No</b>
Size:	<b>M</b>	Impact pad type:	<b>Koroyd</b>
Weight of Sample [kg]:	<b>8.15</b>	Weight of Sample [kg]: <sup>(1)</sup>	<b>0.33</b>
Serial number:	<b>X-49C-068</b>	Serial number: <sup>(1)</sup>	<b>KorSLM</b>
Clip-in weight [kg]:	<b>130</b>	Date of reception:	<b>29.08.2022</b>
Integrated container for rescue system:	<b>Yes</b>		
Volume container [cm <sup>3</sup> ]:			<b>7000 max</b> <b>3500 min</b>
Date of reception:	<b>26.01.2023</b>		

### Test report summary

#### Structual test

#### Impact pad test

Result	<b>POSITIVE</b>	<b>POSITIVE</b>
Place	<b>Villeneuve</b>	<b>Villeneuve</b>
Date	<b>26.01.2023</b>	<b>29.08.2022</b>

### Issue data

Place of declaration: **Villeneuve**  
 Date of issue: **06.10.2021**  
 Managing Director: **Andrea Wigger**  
 Signature: 

Revision 06 : 21.01.2026

Update on the RDT

This revision cancels and replaces the previous one.

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)  
**Air Turquoise SA**, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:2018, and EN12491:2015

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22