

Harness inspection certificate

Inspection certificate number: PH_217.2017

Impact pad number: n/a

Manufacturer data

Manufacturer name: **Sky Guru**
 Representative: **MR & Co. d.o.o.**
 Street: **Cesta v Zgornji Log 67**
 Post code / place: **SI - 1000 Ljubljana**
 Country: **Slovenia**

Sample data:

Harness

Impact pad

Name:	Alpine Lite	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	n/a
Size:	S	Impact pad type:	n/a
Weight of Sample [kg]:	0.235	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	175101AD	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	104	Date of reception:	n/a
Integrated container for rescue system:	n/a		
Volume container [cm ³]:			n/a max n/a min
Date of reception:	18.12.2017		

Test report summary

Structual test

Impact pad test

Result	POSITIVE	n/a
Place	Villeneuve	n/a
Date	18.12.2017	n/a

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **13.05.2019**
 Managing Director: **Alain Zoller**
 Signature:



This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:
 European Standard **EN1651 :1999**, and **EN12491:2015 chapter 5.3.2**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22