

Harness inspection certificate - EN

Inspection certificate number: **PH_331.2021**Impact pad number: **MISC_180.2021**
MISC_181.2021

Manufacturer data

Manufacturer name: **Supair SAS**
 Representative: **Laurent Chiabaut**
 Street: **Parc Altais / 34, rue Adrastée**
 Post code / place: **74650 Chavanod**
 Country: **France**

Sample data:

Harness

Impact pad

Name:	Strike 2	Name Impact pad: ⁽¹⁾	Bump STK2
Type:	ABS	Impact pad integrated: ⁽¹⁾	No
Size:	M	Impact pad type:	Foam
Weight of Sample [kg]:	2.22	Weight of Sample [kg]: ⁽¹⁾	0.457
Serial number:	STK2PSM_V2	Serial number: ⁽¹⁾	BUMPSTK2PS
Clip-in weight [kg]:	120	Date of reception:	16.12.2020
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			
			4700 max
			2900 min
Date of reception:	29.01.2021		

Test report summary

Structural test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	18.02.2021	16.12.2020

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **26.04.2021**
 Managing Director: **Alain Zoller**
 Signature: 

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)
 Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651:2018** and **EN12491:2015**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22