

Harness inspection certificate - LTF

Inspection certificate number: **PH_299.2020**Impact pad number: **PH_299.2020**

Manufacturer data

Manufacturer name: **Woody Valley srl**
 Representative: **Simone Caldana**
 Street: **Via Vienna 92**
 Post code / place: **30121 Trento**
 Country: **Italy**

Sample data:

Harness

Impact pad

Name:	Wani 3	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	M	Impact pad type:	other
Weight of Sample [kg]:	4.16	Weight of Sample [kg]: ⁽¹⁾	n/a
Serial number:	099.0115.001P	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120	Date of reception:	01.04.2020
Integrated container for rescue system:	Yes		
Volume container [cm ³]:			
			5500 max
			2800 min
Date of reception:	01.04.2020		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	27.04.2020	27.04.2020

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **13.05.2020**
 Managing Director: **Alain Zoller**
 Signature: 

This signature approve the validity of the test reports if available; no. 94.21 (test id 02, 03, 13, 09, 04, 14, 07) and no. 94.22 (test id: P, PR)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:
 European Standard **EN1651 :1999**, and **EN12491:2015** - Airworthiness Requirements **LTF NFL II 91/09**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22